

**Labor and Materials**

1	Copper } Connection.....	?	\$ 1.48
1	Lead } Connection.....	1/4	\$ 1.79
1	Curb { Cock } .....	in	\$ 1.79
	{ Valve } .....	3/4	
	{ F.S.&V. } .....	1/4	
1	Service Box { Short 3 1/2 x 4 1/2 } .....		\$ 1.46
	Old returned { Long 4 1/2 x 5 1/2 } .....		
	{ Bull. or Rawls } .....		
27	Ft. .... in. { Copper } Pipe at .....	?	\$ 4.86
	{ Galv. Iron } .....		
	{ Cast Iron } .....		
	Nipples .....	in. at	\$ .....
	Bushings .....	to .....	in. at \$ .....
	Red'g } Couplings.....	to .....	in. at \$ .....
	Inc'g } .....		
	Union.....	in. at	\$ .....
	Meter.....	in. at	\$ .....
	Lbs. Br. Stone at .....		\$ .....
	Lbs. Sand at .....		\$ .....
	Bags Cement at .....		\$ .....
	Paving Brick { Mack } at .....		\$ .....
	{ Red } .....		
	{ Asphalt } .....		
	Lead Joints at .....		\$ .....
	Leadite Joints at .....		\$ .....
12	Hrs. Foreman at .....		\$ 7.50
17	Hrs. Common Labor at .....		\$ 5.40
	Hrs. Common Labor at .....		\$ .....
	Hrs. Mason at .....		\$ .....
	Hrs. Masons Helper at .....		\$ .....
	Hrs. Compressor at .....		\$ .....
	Compensation Ins .....		\$ .40
	Trucking .....		\$ 1.00
	Builders Use of Water <i>Patrol</i> .....		\$ 5.00
Total \$			28.89

532-109 121

Labor and Material Report *Aug 24* 19*33*

93 Lawrence St

Elev. of Main at tap *4 1/2*

12 Main

Gate at ● ● Gate at

● Curb Box

9515127

*OK G/M*