

Labor and Materials

2	Copper } Connection		\$ 2.70	
	Lead }			
4	Curb } Cock Valve	3	\$ 2.39	
	T.S. & V. }			
	Service Box } Short 3"x4 1/2"		\$ 1.55	
	Old returned } Long 4"x5 1/2"			
			Buff or Railway	
9	Ft. in. } Copper Pipe at	3/4	\$ 2.43	
			Galv Iron	
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g } Couplings	to in. at	\$	
	Inc'g }			
	Union	in. at	\$	
	Meter	in. at	\$	
	Lbs. Br. Stone	at	\$	
	Lbs. Sand	at	\$	
	Bags Cement	at	\$	
	Paving Brick } Mack	} at	\$	
				Red
				Asphalt
	Lead Joints	at	\$	
	Leadite Joints	at	\$	
6	Hrs. Foreman	at	\$ 3.75	
16	Hrs. Common Labor	at	\$ 7.20	
	Hrs. Common Labor	at	\$	
	Hrs. Mason	at	\$	
	Hrs. Mason's Helper	at	\$	
3	Hrs. Compressor	at	\$ 4.50	
	Compensation Ins		\$ 2.33	
	Trucking		\$ 1.-	
	Builders' Use of Water		\$ 5.-	
Total \$			30.85	

01-7 18 LAWRENCE ST
 Labor and Material Report 1-5 1931
 10 Lawrence St

18" 22" Lawrence St
 Curb Box
 Traver St.

4 Main Eley of Main at tap 5 1/2
 Gate at ● Gate at ●
 ● Curb Box

add tap to be dug up