

LABOR AND MATERIALS

| | | | | | |
|----|-------------------------------|--|------------|----|-------|
| 1 | Copper Lead | Connection | 3/4" | \$ | 3.08 |
| 1 | Curb | Cock Valve T.S. & V. | 3/4 in. | \$ | 3.89 |
| 1 | Service box Old returned | Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway | | \$ | 4.32 |
| 19 | Ft. | Copper G.I. Pipe at | 3/4 in. 45 | \$ | 8.55 |
| | Nipples | in. at | | \$ | |
| | Bushings | to in. at | | \$ | |
| | Red'g Inc'g | Coupl'gs. to in. at | | \$ | |
| | Union | in. at | | \$ | |
| | Meter | in. at | | \$ | |
| | Lead Joints at | | | \$ | |
| | Compound Joints at | | | \$ | |
| | Maintenance Foreman | | | \$ | 39.53 |
| | Hrs. Water Maint. Man-1 at | | | \$ | |
| 10 | Hrs. Water Maint. Man-2 at | 1.613 | | \$ | 16.13 |
| | Hrs. Garage Foreman at | | | \$ | |
| 18 | Hrs. Labor at | 1.30 | | \$ | 23.40 |
| | Hrs. Compressor at | | | \$ | |
| | Compensation Ins. at | \$56.86 per C | | \$ | 2.25 |
| | Trucking | | | \$ | 1.50 |
| | Pav't Patch | | | \$ | 12.60 |
| | Tap by Gifford & Co. 10-16-56 | | | \$ | |
| | O'head | | | \$ | |
| | | | | \$ | 75.72 |

6312

Lawton St. Ave. No. 183

Name of Owner Benjamin

Labor and Mat'l. Report Oct. 16 1956

