

Labor and Materials

1	Lead Connection	\$
1	Curb Cock	\$
1	Service Box { Short 3 1/2 x 4 1/2	\$
	Old returned { Long 4 1/2 x 5 1/2	\$
	(-Buffalo	\$
15	Ft. 3/4 in. G. I. Pipe at	\$
	Nipples.....in. at	\$
	Bushings.....to.....in. at	\$
	Red'g Coup.....to.....in. at	\$
	Inc'g Coup.....to.....in. at	\$
	Union.....in. at	\$
	Meter.....in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack	} at	\$
	Red		
	Asphalt		
1	Hrs. Foreman at	\$
4	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
yet	Builders' Use of Water	\$
	Truck 100	\$
 at	\$
 at	\$
 at	\$
 at	\$
	Total	\$ 101.95	

Labor and Material Report

1923

12' Tap at ²⁴⁷ Lawton Ave



11" Main Elev. of Main at tap 11.11

Gate at ● ● Gate at

● Curb Box