

Labor and Materials

1	Copper	Connection	3	\$ 3.20
	Lead			
	Curb	Cock Valve T.S. & V.	1 in.	\$ 1.00
1	Service Box	Short 3" x 4" Long 4" x 5" Buff. or Rdway		\$ 1.30
	Old returned			
20	Pt.	Copper Galv. Iron Cast Iron	3 in. Pipe at	\$ 4.40
	Nipples		in. at	\$
	Bushings		to in. at	\$
	Red'g Inc'g	Couplings	to in. at	\$
	Union		in. at	\$
	Meter		in. at	\$
	Lbs. Br. Stone		at	\$
	Lbs. Sand		at	\$
	Bags Cement		at	\$
	Paving Brick	Mack Red Asphalt	at	\$
	Lead Joints		at	\$
	Leadite Joints		at	\$
4	Hrs. Foreman		at 62.5¢	\$ 2.50
1.6	Hrs. Common Labor		at 50¢	\$ 8.00
1.6	Hrs. Common Labor		at 40.5¢	\$ 6.50
	Hrs. Mason		at	\$
	Hrs. Mason's Helper		at	\$
	Hrs. Compressor		at	\$
	Compensation Ins.			\$ 45
	Trucking			\$ 1.00
	Builders' Use of Water			\$

Total \$28.35

26-189

Labor and Material Report

19 22

Nov 12-14 Sawton Ave



Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

Old taps to be dug up.