

LABOR AND MATERIALS

Copper	} Connection		\$	
Lead			\$	
Curb	} Cock Valve T. S. & V. }	in.	\$	
Service box		} Short 3½ x 4½ Long 4½ x 5½ }		\$
Old returned				\$
484 Ft. 2 in.	} Copper Pipe	Pipe at	\$	
			\$	
Nipples	in. at	\$		
Bushings	to in. at	\$		
Red'g Inc'g } Coupl'gs	to in. at	\$		
Union	in. at	\$		
Meter	in. at	\$		
Compound Joints	at	\$		
Maintenance Foreman		\$		
Hrs. Water Maint. Man—1	at	\$		
Hrs. Water Maint. Man—2	at	\$		
Hrs. Garage Foreman	at	\$		
Hrs. Labor—	at	\$		
Hrs. Compressor	at	\$		
Trucking		\$		
Pav't Patch		\$		
		\$		
		\$		
		\$		
		\$		

LEONARD

St. No. 40(P)

Name of Owner

POST STAR

Labor and Mat'l. Report

5-25 2000

#39

73' 74'

● Curb Box

6" Main

Elev. of Main at tap

Gate at ●

● Gate at

● Curb Box

TIES FROM HOUSE ACROSS THE STREET