

Labor and Materials

1	Copper } Connection.....	2	\$1.25
1	Lead }	1/4
1	Curb { Cock Valve U.S.&V. }	3	\$1.70
1	Service Box { Short 3 1/2 x 4 1/2 }	1	\$1.37
	Old returned { Long 4 1/2 x 5 1/2 }		
4	Ft. 3/4 in. { Copper Galv. Iron Cast Iron } Pipe at 13.12	54
	Nipples		\$.....
	Bushings		\$.....
	Red'g } Couplings.....		\$.....
	Inc'g }		\$.....
	Union.....		\$.....
	Meter.....		\$.....
	Lbs. Br. Stone at		\$.....
	Lbs. Sand at		\$.....
	Bags Cement at		\$.....
	Paving Brick { Mack Red Asphalt } at		\$.....
	Lead Joints at		\$.....
	Leadite Joints at		\$.....
2	Hrs. Foreman at	6.21 x	\$1.25
6	Hrs. Common Labor at	45	\$2.70
	Hrs. Common Labor at		\$.....
	Hrs. Mason at		\$.....
	Hrs. Masons Helper at		\$.....
	Hrs. Compressor at		\$.....
	Compensation Ins		\$15
	Trucking		\$1-
	Builders Use of Water		\$.....
Total			\$9.96

1935-21

Labor and Material Report

July 18 1935

33 LEONARD ST



6" Main

Elev. of Main at tap 4 1/2

Gate at ●

● Gate at

TAX ID # 303.17-5-10

● Curb Box

Old tap shut off at main
No hole in Street main
under S. & W. walk.

AM