

**Labor and Materials**

.....Copper	} Connection.....	.....	.....
.....Lead			
.....Curb	} Cock Valve T.S.&V. }	.....in	.....
.....Service Box			
.....Old returned	} Short 3½x4½ Long 4½x5½ Buff. or Rdwar }	.....	.....
.....Ft.....in.			
.....Nipples	} Copper Galv. Iron Cast Iron }	.....in. at	.....
.....Bushings			
.....Red'g Inc'g	} Couplings.....to.....in.at	.....	.....
.....Union			
.....Meter	.....in. at	.....	.....
.....Lbs. Br. Stone	at	.....	.....
.....Lbs. Sand	at	.....	.....
.....Bags Cement	at	.....	.....
.....Paving Brick	} Mack Red Asphalt }	at	.....
.....Lead Joints			
.....Leadite Joints			
.....Hrs. Foreman	at	.....	.....
.....Hrs. Common Labor	at	.....	.....
.....Hrs. Mason	at	.....	.....
.....Hrs. Masons Helper	at	.....	.....
.....Hrs. Compressor	at	.....	.....
.....Compensation Ins	.....	.....	.....
.....Trucking	.....	.....	.....
.....Builders Use of Water	.....	.....	.....
Total \$.....			.....

Leonard St 51-53-53R  
 Labor and Material Report Dec 29 1922  
 Kendrick & Brown  
 Garage Barn  
 51-53-53R  
 22-0  
 Curb Box

---

.....Main	Elev. of Main at tap
Gate at ●	● Gate at

---

● Curb Box  
 Shut off for garage + barn  
 on Leonard St  
 Kendrick & Brown Co.

*(Signature)*