

Labor and Materials

1	Lead Connection	\$
1	Curb Cock	\$
1	Service Box (Short 24 x 4 Old returned (Long 41 x 5) Buffalo)	\$
12	Ft. in. G. I. Pipe at	\$
	Nipples in. at	\$
1	Bushings $\frac{3}{4}$ to $\frac{1}{2}$ in. at	\$
1	Inc'g Coup. to in. at BRASS	\$
	Inc'g Coup. to in. at	\$
	Union in. at	\$
	Meter in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick (Mack Red Asphalt) at	\$
2	Hrs. Foreman at	\$
13	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
	Builders' Use of Water	\$
	at	\$
	at	\$
	at	\$
	at	\$
	at	\$
	at	\$
	Total	\$

18
Labor and Material Report Sep 9 1925
 14 ROBERTS AVE
 LEXINGTON

6" Main
 Elev. of Main at tap 6"

Gate at ● Gate at ●

Curb Box