Labor and Materials

1	[illegible] Connection	3/4	$
1	Curb Cock	3/4	$
1	Service Box Old returned { Short 3½ x 4½ / Long 4½ x 5½ / Buffalo }		$
12	Ft. 3/4 in. [illegible] Pipe at	COP	$
	Nipples in. at		$
1	Bushings 3/4 to 1/2 in. at		$
1	[illegible] Coup to in. at	BRASS	$
	Inc'g Coup to in. at		$
	Union in. at		$
	Meter in. at		$
	Cu. Yds. Br. Stone at		$
	Cu. Yds. Sand at		$
	Bags Cement at		$
	Paving Brick { Mack / Red / Asphalt } at		$
2	Hrs. Foreman at		$
13	Hrs. Common Labor at		$
	Hrs. Mason at		$
	Hrs. at		$
	Hrs. at		$
	Builders' Use of Water		$
	at		$
	at		$
	at		$
	at		$
	Total		$

Labor and Material Report

25 Lexington Sept 9 1920

14 ~~ROBERTS~~ AVE

NO PORCH ON HOUSE

6" Main

Elev. of Main at tap 6'

Gate at ● ● Gate at

TAX ID # 302.12-10-30