


Labor and Materials

1	Lead Connection	\$	
1	Curb Cock	\$	
1	Service Box	{ Short 3 1/2 x 4 1/2	\$	
	Old returned	{ Long 4 1/2 x 6 1/2	\$	
		{ Buffalo	\$	
2 1/2	Ft. in. G. I. Pipe at	cap	\$	
	Nipples in. at	\$	
	Bushings to..... in. at	\$	
1	Inc'g Coup to..... in. at	\$	
	Inc'g Coup to..... in. at	\$	
	Union in. at	\$	
	Meter in. at	\$	
	Cu. Yds. Br. Stone at	\$	
	Cu. Yds. Sand at	\$	
	Bags Cement at	\$	
	Paving Brick	{ Mack	} at	
		{ Red		} at
		{ Asphalt		
2 1/2	Hrs. Foreman at	\$	
1 1/2	Hrs. Common Labor at	\$	
	Hrs. Mason at	\$	
	Hrs. at	\$	
	Hrs. at	\$	
	Builders' Use of Water	\$	
	 at	\$	
	 at	\$	
	 at	\$	
	 at	\$	
	Total	\$.....		

29 Labor and Material Report Sept 16 1925

Lexington
 13 ~~St. Pauls Ave~~
 VACANT LOT
 29 Sewer Manhole

 24.5' x 49.3'
 Curb Box

6" Main Elev. of Main at tap 6'

Gate at ● Gate at ●

Curb Box