

LABOR AND MATERIALS

Copper } Connection _____ \$ _____
 Lead }
 Curb } Cock } _____ in. \$ _____
 } Valve }
 } T. S. & V. }
 Service box { Short 3½ x 4½ }
 Old returned { Long 4½ x 5½ }
 { Buff or Rdway } _____ \$ _____
 24' Ft. 8" in. { Copper } Pipe at 3/4" \$ _____
 { G. I. }
 { C. I. }
 Nipples _____ in. at _____ \$ _____
 Bushings _____ to _____ in. at _____ \$ _____
 Red'g }
 Inc'g } Coupl'gs _____ to _____ in. at _____ \$ _____
 Union _____ in. at _____ \$ _____
 Meter _____ in. at _____ \$ _____
 Lead Joints at _____ \$ _____
 Compound Joints at _____ \$ _____
 Maintenance Foreman _____ \$ _____
 Hrs. Water Maint. Man—1 at _____ \$ _____
 Hrs. Water Maint. Man—2 at _____ \$ _____
 Hrs. Garage Foreman _____ at _____ \$ _____
 Hrs. Labor _____ at _____ \$ _____
 Hrs. Compressor at _____ \$ _____
 Compensation Ins. at \$ _____ per C _____ \$ _____
 Trucking _____ \$ _____
 Pav't Patch _____ \$ _____
 Tap by Trecco + Co _____ \$ _____
 O'head _____ \$ _____
 _____ \$ _____

St-
Pt. Ave. No. 7

LEXINGTON

Name of Owner
Raymond Wyther

Labor and Mat'l. Report Aug 11 1977

7
6" Main Elev. of Main at tap 7'

56' 7" 57' 0"

● Curb Box

Gate at ● ● Gate at

● Curb Box

Re measured 8-11-77

LSM-SC-6-1-67