

Labor and Materials		
1	Brass Lead Connection $\frac{3}{4}$	\$
1	Curb Cock $\frac{3}{4}$	\$
1	Service Box (Short $3\frac{1}{2} \times 4\frac{1}{2}$) Old returned 12×15 Buffalo	\$
9	Ft. $\frac{3}{4}$ in. Gal. Pipe at	\$
	Nipples... in. at	\$
1	Bushings $\frac{3}{4}$ to $\frac{1}{2}$ in. at	\$
	Red'g Coup... to... in. at	\$
	Inc'g Coup... to... in. at	\$
	Union... in. at	\$
	Meter... in. at	\$
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick { Mack Red Asphalt } at	\$
1.4	Hrs. Foreman at	\$
2	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at at	\$
	Hrs. at	\$
2.5	Builders' Use of Water	\$
	Trucks 100	\$
	at	\$
	at	\$
	at	\$
	Total	\$

34
Labor and Material Report
1-11-1925 Oct 8 1925
30 Roberts Ave

PORE 4
34
Curb Box

Elev. of Main at tap 5'

6' Main

Gate at ● Gate at

● Curb Box