Labor and Materials

1	~~Lead~~ Connection	3/4	$
1	Curb Cock	3/4	$
1	Service Box Old returned { Short 3½ x 4½ / ~~Long 4½ x 5½~~ / Buffalo }		$
17	Ft. 3/4 in. ~~G.I.~~ Pipe at Cost		$
	Nipples in. at		$
1	Bushings 3/4 to 1/2 in. at		$
	Red'g Coup to in. at		$
	Inc'g Coup to in. at		$
	Union in. at		$
	Meter in. at		$
	Cu. Yds. Br. Stone at		$
	Cu. Yds. Sand at		$
	Bags Cement at		$
	Paving Brick { Mack / Red / Asphalt } at		$
2	Hrs. Foreman at		$
13	Hrs. Common Labor at		$
	Hrs. Mason at		$
	Hrs.	at	$
	Hrs.	at	$
	Builders' Use of Water		$
		at	$
		at	$
		at	$
		at	$
		Total	$

8

Labor and Material Report 19

Lexington

4 ROBERTS AVE

6" Main

Elev. of Main at tap 6'

Gate at ●

● Gate at

● Curb Box

17