

Labor and Materials

1	Lead Connection	\$
1	Curb Cock	\$
1	Service Box (Short 3" x 4")	\$
	Old returned (Long 4" x 5")	
2 1/2	Ft. 3/4 in. C.I. Pipe at	\$
1	Nipples 1/2 in. at	\$
1	Bushings 1/2 to 3/4 in. at	\$
1	Reddy Coup to 1/2 in. at	\$
	Inc'g Coup to 1/2 in. at	\$
2	Union 1/2 in. at	\$
	Meter 1/2 in. at	
	Cu. Yds. Br. Stone at	\$
	Cu. Yds. Sand at	\$
	Bags Cement at	\$
	Paving Brick (Mack Red Asphalt) at	\$
2 1/2	Hrs. Foreman at	\$
1 1/2	Hrs. Common Labor at	\$
	Hrs. Mason at	\$
	Hrs. at	\$
	Hrs. at	\$
	Builders' Use of Water	\$
	at	\$
	at	\$
	at	\$
	at	\$
	at	\$
	Total	\$

Labor and Material Report

19

35 ROBERTS AVE



Curb Box

Lexington Ave

6" Main

Elev. of Main at tap

Gate at

Gate at

Curb Box