

### Labor and Materials

Copper } Connection	3	\$ 2.60
Lead } Connection		
Curb } Cock	4	\$ 7.27
} Valve		
} T. S. & V.	3	
Service Box } Short 3/4x4 1/2	4	\$ 1.38
} Long 1 1/2x5 1/2		
} Built on Rdway		
10 Ft. in. } Copper	3	\$ 1.80
} Galv. Iron		
} Cast Iron		
Nipples	in. at	\$
Bushings	to in. at	\$
Red'g } Couplings	to in. at	\$
Inc'g }		
Union	in. at	\$
Meter	in. at	\$
Lbs. Br. Stone	at	\$
Lbs. Sand	at	\$
Bags Cement	at	\$
Paving Brick } Mack	} at	\$
} Red		
} Asphalt		
Lead Joints	at	\$
Leadite Joints	at	\$
2 Hrs. Foreman	at	\$ 1.25
7 Hrs. Common Labor	at	\$ 3.15
Hrs. Common Labor	at	\$
Hrs. Mason	at	\$
Hrs. Mason's Helper	at	\$
Hrs. Compressor	at	\$
Compensation Ins.		\$
Trucking		\$ 1.14
Builders' Use of Water	Potter (Summer)	\$
Total \$		18.59

31-224

62

Oct 29

193

### Labor and Material Report

42 Robert's Ave  
Lexington  
62



Main

Elev of Main at tap

Gate at ●

● Gate at

● Curb Box

New House