

## Labor and Materials

Copper	Lead	Connection	.....	\$	
	}	Cock Valve T. S. & V.	..... in	\$	
1	Service Box	Short 3/4 x 1/2	.....	\$	
	Old returned	Long 4 1/2 x 5 1/2	.....	\$	
		Buff or Rdway	.....	\$	
11	Ft. 3/4 in.	Copper	} Pipe at	\$	- 1992
		Cast Iron		\$	
		Cast Iron		\$	
	Nipples	..... in. at	..... in. at	\$	
	Bushings	..... to	..... in. at	\$	
	Red'g Inc'g	Conplings	..... to	..... in. at	\$
	Union	..... in. at	.....	\$	
	Meter	..... in. at	.....	\$	
	Lead Joints	at	.....	\$	
	Leadite Joints	at	.....	\$	
	Hrs. Foreman	at	.....	\$	
	Hrs. Chauffeur	at	.....	\$	
	Hrs. Tapper	at	.....	\$	
	Hrs. Labor	at	.....	\$	
	Hrs. Labor	at	.....	\$	
	Hrs. Compressor	at	.....	\$	
	Compensation Ins.	.....	.....	\$	
	Trucking	.....	.....	\$	
	Builders Use of Water	.....	.....	\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	
				\$	

St. 79  
 Pl. 52  
 Ave. No. 52

Leighton

---

Name of Owner  
*D. K. Roe*

---

Labor and Mat'l. Report Sept 13 1916

74

● Curb Box

Use long short off  
*W. K. Roe*

---

Main Elev. of Main at tap.....

---

Gate at ● ● Gate at

---

● Curb Box