LABOR AND MATERIALS

1	Copper Lead } Connection 3/4	$ 1.31
1	Curb { Cock Valve T. S. & V. } 3/4 in.	$ 1.75
1	Service Box Old returned { Short 3⅛x4⅛ Long 4⅛x5⅛ Buff or Rdway }	$ 1.60
26	Ft. 3/4 in. { Copper Galv Iron Cast Iron } Pipe at 18	$ 4.68
	Nipples in. at	$
	Bushings to in. at	$
	Red'g Inc'g } Couplings to in. at	$
	Union in. at	$
	Meter in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
5	Hrs. Chauffeur at 62½	$ 3.13
	Hrs. Tapper at	$
16	Hrs. Labor at 45	$ 7.20
	Hrs. Labor at	$
	Hrs. Compressor at	$
	Compensation Ins.	$ .32
	Trucking	$ 1.—
	Builders Use of Water ½ Patch (Sum)	$ 2.50
	Truck Time	$
		$
		$
		$ 23.49

1 4 6 - 1940 77

St. ~~Pl.~~ 58

Lexington Ave. No. 75

Name of Owner

LaPoint

Labor and Mat'l. Report Nov 1 1940

6 Main

Elev. of Main at tap 5—

Gate at ● ● Gate at

● Curb Box