

Labor and Materials

Copper } Connection.....	3	\$ 2.70
Lead }		
Curb } Cock Valve }	4	\$ 2.39
} T-S & V. }	3	
Service Box } Short 3" x 4" }		\$ 1.45
Old returned } Long 4" x 5" }		
} Buff. or Rdway }		
2.6 Ft. } in. }	3	\$ 7.02
} Copper } Pipe at.....	4	
} Galv. Iron }		
} Cast Iron }		
Nipples.....	in. at.....	\$.....
Bushings.....	to..... in. at.....	\$.....
Red'g } Couplings.....	to..... in. at.....	\$.....
Inc'g }		
Union.....	in. at.....	\$.....
Meter.....	in. at.....	\$.....
Lbs. Br. Stone at.....		\$.....
Lbs. Sand at.....		\$.....
Bags Cement 'at.....		\$.....
Paving Brick } Mack } at.....		\$.....
} Red }		
} Asphalt }		
Lead Joints at.....		\$.....
Leadite Joints at.....		\$.....
3 Hrs. Foreman at.....		\$ 1.88
1.6 Hrs. Common Labor at.....		\$ 7.20
Hrs. Common Labor at.....		\$.....
Hrs. Mason at.....		\$.....
Hrs. Mason's Helper at.....		\$.....
Hrs. Compressor at.....		\$.....
Compensation Ins.....		\$ 28
Trucking.....		\$ 1.-
Builders' Use of Water.....		\$ 5.-
Total \$.		28.92

Labor and Material Report

Oct. 18 1920

4 Liberty Ave.

● Curb Box



● Curb Box

Yewhouse