LABOR AND MATERIALS

1 ~~Copper~~ Lead } Connection 1/2" ____ $____

1 Curb { Cock / Valve / T. S. & V. } 5/8 in. ____ $____

1 Service Box ~~Old returned~~ { Short 3½x4½ / Long 4½x5½ / Buff. or Rdway } ____ $____

12 Ft. 3/4 in. { Copper / Galv Iron / Cast Iron } Pipe at ____ $____

____ Nipples ____ in. at ____ $____

____ Bushings ____ to ____ in. at ____ $____

Red'g / Inc'g } Couplings ____ to ____ in. at ____ $____

____ Union ____ in. at ____ $____

____ Meter ____ in. at ____ $____

____ Lead Joints at ____ $____

____ Leadite Joints at ____ $____

____ Hrs. Foreman at ____ $____

____ Hrs. Chauffeur at ____ $____

____ Hrs. Tapper at ____ $____

____ Hrs. Labor at ____ $____

____ Hrs. Labor at ____ $____

____ Hrs. Compressor at ____ $____

____ Compensation Ins. ____ $____

____ Trucking ____ $____

____ Builders Use of Water ____ $____

____ $____

____ $____

____ $____

____ $____

$____

~~St.~~
~~Pl.~~
Liberty Ave. No. 5

Name of Owner

Labor and Mat'l. Report June 2 1917

● **Curb Box**

6" **Main** **Elev. of Main at tap**

Gate at ● ● **Gate at**

● **Curb Box**