

Labor and Materials

Copper	}	Connection.....	\$.....
Lead			
Curb	}	Cock	} in \$.....
		Valve	
		T. S. & V.	
Service Box	}	Short 3½ x 4½	} \$.....
Old returned		Long 4½ x 5½	
		Buff. or Rdway	
Ft. in.	}	Copper	} Pipe at \$.....
		Galv Iron	
		Cast Iron	
Nipples in. at.....			
Bushings to..... in. at.....			\$.....
Red'g	}	Conplings..... to..... in. at.....	\$.....
Inc'g			
Union in. at.....			\$.....
Meter in. at.....			\$.....
Lead Joints at.....			\$.....
Leadite Joints at.....			\$.....
Hrs. Foreman at.....			\$.....
Hrs. Chauffeur at.....			\$.....
Hrs. Tapper at.....			\$.....
Hrs. Labor at.....			\$.....
Hrs. Labor at.....			\$.....
Hrs. Compressor at.....			\$.....
Compensation Ins.			\$.....
Trucking			\$.....
Builders Use of Water			\$.....
			\$.....
			\$.....
			\$.....
			\$.....
			\$.....
			\$.....
			\$.....

St. ?
 Pl. ?
 Ave. No.

Liberty

Name of Owner
L. H. Sherman

Labor and Mat'l. Report *5-15-18* 19

● Curb Box

6 Main
Elev. of Main at tap.....

Gate at ●
● Gate at

● Curb Box