

Labor and Materials

Copper } Connection.....	\$ 320
Lead }	
Curb { Cock }	\$ 1.00
{ Valve }	
{ T. S. & V. }	
Service Box { Short 3 1/2 x 4 1/2 }	\$ 1.30
Old returned { Long 4 x 5 1/2 }	
{ Buff. or Rdway }	
6 Ft. 3/4 in. { Copper } Pipe at.....	\$
{ Galv. Iron }	
{ Cast Iron }	
Nipples..... in. at.....	\$
Bushings..... to..... in. at.....	\$ 1.07
Red'g } Couplings..... to..... in. at.....	\$ 1.5
{ In'g }	
Union..... in. at.....	\$
Meter..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick { Mack } at.....	\$
{ Red }	
{ Asphalt }	
Lead Joints at.....	\$
Leadite Joints at.....	\$
Hrs. Foreman at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$
Trucking.....	\$ 1.50
Builders' Use of Water.....	\$
Total \$.....	

Labor and Material Report

1921

32 Lincoln Ave.



Crandell St.

15" Main

Elev. of Main at tap 5'

Gate at ●

● Gate at

● Curb Box

Old top sheet
886