

8/11/80

Labor and Materials

<u>3/4</u> Copper	Connection.....	.....	\$ .....		
Lead					
Curb	Cock Valve T. S. & V. }	..... in .....	\$ .....		
Service Box					
Old returned					
<u>35</u> Ft. ....	in. }	Short 3½ x 4½ Long 4½ x 5½ Buff. or Rdway	Pipe at .....		
				Copper	\$ .....
Cast Iron					
Nipples	in. at .....	\$ .....			
Bushings	to .....	in. at .....	\$ .....		
Red'g Inc'g	Conplings.....to .....	in. at .....	\$ .....		
Union					
Meter	in. at .....	\$ .....			
Lead Joints	at .....	\$ .....			
Leadite Joints	at .....	\$ .....			
Hrs. Foreman	at .....	\$ .....			
Hrs. Chauffeur	at .....	\$ .....			
Hrs. Tapper	at .....	\$ .....			
Hrs. Labor	at .....	\$ .....			
Hrs. Labor	at .....	\$ .....			
Hrs. Compressor	at .....	\$ .....			
Compensation Ins.	.....	\$ .....			
Trucking	.....	\$ .....			
Builders Use of Water	.....	\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			
		\$ .....			

St. PL. Ave. No. 33

Lincoln

---

Name of Owner  
Langston Woodbury

---

Labor and Mat'l. Report Nov. 1 1927

---

---

Main Elev. of Main at tap.....

Gate at ● ● Gate at

---

● Curb Box

*re-measured 8/12/80 saw measurements*