LABOR AND MATERIALS

1	Copper / ~~Lead~~ Connection 3/4	$ 1.23
1	Curb { Cock / Valve / T. S. & V. } 3/4 in.	$ 1.68
1	Service Box Old returned { Short 3½x4½ / Long 4½x5½ / Buff. or Rdway }	$ 1.75
13 Ft. 3/4 in.	{ Copper / ~~Galv Iron~~ / ~~Cast Iron~~ } Pipe at	$ 1.95
	Nipples ____ in. at	$
	Bushings ____ to ____ in. at	$
	Red'g / Inc'g Couplings ____ to ____ in. at	$
	Union ____ in. at	$
	Meter ____ in. at	$
	Lead Joints at	$
	Leadite Joints at	$
	Hrs. Foreman at	$
7	Hrs. Chauffeur at 62½	$ 1.25
3	Hrs. Tapper at	$ 1.88
18	Hrs. Labor at 45	$ 8.10
	Hrs. Labor at	$
1	Hrs. Compressor at 87½	$ 88
1	Compensation Ins.	$ 35
	Trucking	$ 1.—
	Builders Use of Water hospital (B.T.)	$
	Tap by Hassell	$
		$
		$
		$
		$ 19.07

1 2 6 - 1938

~~St.~~
~~Pl.~~
Linwood Ave. No. 38

Name of Owner

F L H Meyer

Labor and Mat'l. Report Aug 31 19 38

16 Main

Elev. of Main at tap 41½

Gate at ●

● Gate at

● Curb Box

Old Tap Shut off