

LABOR AND MATERIALS

1	Copper Lead	Connection	1 1/4"	\$
1	Curb	Cock Valve T.S. & V.	1 1/4"	\$
1	Service box Old returned	Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway		\$
22	Ft. 1/4 in.	Copper G.I. G.I. Pipe at		\$
	Nipples	in. at	Brass	\$
1	Bushings	1/4 to 1 in. at		\$
	Red'g } Inc'g }	Coupl'gs	to in. at	\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.	at \$ per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by Miller & Co			\$
	7-22-60			\$
	O'head			\$

St. No. \_\_\_\_\_  
Pl. No. 26+28  
Ave. No. \_\_\_\_\_

Logan

Name of Owner  
Broughton Co. Inc.

Labor and Mat'l. Report July 22 19 60.

6" Main      Elev. of Main at tap 5'

Gate at ●      ● Gate at

● Curb Box

1/4" Tap  
Large Bussalo box.

LSM-5C-2-5 56