

LABOR AND MATERIALS

Copper Lead	{ Connection Skinner Service 2" Saddle	\$	
1 Curb	{ Cock Valve T.S. & V. } 3/4 in.	\$	2.70
1 Service box Old returned	{ Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway }	\$	4.25
13 Ft. 3/4 in.	{ Copper C.I. } Pipe at 35	\$	4.55
1 Nipples	1" in. at 5" long	\$	
1 Bushings	1" to 3/4 in. at	\$	
Red'g Inc'g	{ Coupl'gs } to in. at	\$	
1 Union	3/4 in. at adapter	\$	60.00
Meter	in. at	\$	4.00
Lead Joints at		\$	0
Compound Joints at		\$	
8 1/2 Hrs. Water Maint. Man-1 at	1.12	\$	9.50
27 Hrs. Water Maint. Man-2 at	1.02	\$	27.54
Hrs. Labor	at	\$	
30 1/2 Hrs. Labor	at 91	\$	27.76
Hrs. Compressor at		\$	
Compensation Ins. at \$	per C.	\$	1.44
Trucking		\$	1.00
Pav't Patch		\$	12.83
1-1" Curb box old		\$	
1 copy Magnifying		\$	
O'head		\$	

20-1950 ✓

Logan

Str. _____
Pl. _____
Ave. No. 15

Name of Owner
Ashford

Labor and Mat'l. Report
April 12 1950

29'5" 42'10" Curb Box

6" - 1960
2" Main

Elev. of Main at tap 9'

Gate at • Gate at •

• Curb Box

LSM-5C 10-21-49