

Labor and Materials

1	Copper	} Connection ^{1/2}		\$ 1.75
1	Lead			
1	Curb	} Cock Valve T.S.&V. ^{3/4} in		\$ 1.70
1	Service Box			
	Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff. or Rdway		\$ 1.45
11	Ft. ^{3/4} in.			
		} Copper Galv. Iron Cast Iron	Pipe at 1317	\$ 1.49
	Nipples			
	Bushings			
	Red'g Inc'g	} Couplings		
	Union			
	Meter			
	Lbs. Br. Stone			
	Lbs. Sand			
	Bags Cement			
	Paving Brick	} Mack Red Asphalt		
	Lead Joints			
	Leadite Joints			
40	Hrs. Foreman		6.24	\$ 7.50
54	Hrs. Common Labor		45	\$ 24.30
	Hrs. Common Labor			
	Hrs. Mason			
	Hrs. Masons Helper			
	Hrs. Compressor			
	Compensation Ins			\$ 1.86
	Trucking			\$ 2.00
	Builders Use of Water	Patch		\$ 2.50
Total				\$ 67.55

1935-72

Labor and Material Report

1935

1/2 tap at 11 Logan Ave



6" - 1960

Main

Elev. of Main at tap 8

Gate at ●

● Gate at

● Curb Box

New tap near House

[Handwritten signature]