

### LABOR AND MATERIALS

1	Copper Lead } Connection	3/4			\$ 2.94
1	Curb { Clock Valve F. S. & V. }	3/4	in.		\$ 3.71
1	Service box Old-returned	{ Short 3/4 X 4/4 Long 4/4 X 5/4 Buff for Rdway }			\$ 5.90
8	Ft.	3/4	in.	{ Copper Galv. Iron Cast Iron } Pipe at	30 \$ 2.40
	Nipples		in. at		\$
	Bushings		to in. at		\$
	Red'g Inc'g }	Couplings	to in. at		\$
	Union		in. at		\$
	Meter		in. at		\$
	Lead Joints at				\$
	Compound Joints at				\$
	Hrs. Foreman at				\$
5	Hrs. <del>Chauffeur</del>	W.M.M. ✓		91	\$ 4.55
	Hrs. Tapper at				\$
11	Hrs. Labor at			90	\$ 8.80
	Hrs. Labor at				\$
3	Hrs. Compressor at	1.20			\$ 3.60
	Compensation Ins.				\$ 29
	Trucking				\$ 1.00
	Builders Use of Water				\$
	<i>Toply Magellan</i>				\$
					\$
					\$
					\$
					\$
					\$ 33.19

~~158~~      Lot # 39

158      St.      34

*McArthur Drive*      Pl.      16

Ave. No.      16

---

Name of Owner

*A. F. Brown*

---

Labor and Mat'l. Report      *Feb 25*      19*48*

---

---

12      Main      Elev. of      5  
Main at tap      Main at tap

Gate at ●      ● Gate at

---

● Curb Box

LSM-5C-6-1-48