

Labor and Materials

Copper } Connection.....		\$ 3.20
Lead }		
Curb { Cock Valve }	in. 3	\$ 1.00
{ T.S. & V. }		
Service Box } Short 3/4x4 1/2 }		\$ 1.30
Old returned } Long 1 1/2x5 1/2 }		
{ Buff. or Rdway }		
15 Ft. in. } Copper } Pipe at.....	3	\$ 3.30
{ Cast Iron }		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement at.....		\$
Paving Brick { Mack } at.....		\$
{ Red }		
{ Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
9 Hrs. Foreman at.....		\$ 18.8
8 Hrs. Common Labor at.....		\$ 30.0
6 Hrs. Common Labor at.....		\$ 24.4
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
Hrs. Compressor at.....		\$
Compensation Ins.....		\$ 19
Trucking.....		\$ 1.00
Builders' Use of Water.....		\$
Total \$		173.1

28-149 17
 Labor and Material Report Cert 27 1929

11 Madison St



● Curb Box

6"
 4" Main

Elev of Main at tap 4'

Gate at ●

● Gate at

● Curb Box