

Labor and Materials

1	Lead Connection	at	\$.
1	Curb Cock	at	\$.
1	Service Box (Short $3\frac{1}{2}$ x $4\frac{1}{2}$) Old returned (Long $4\frac{1}{2}$ x $5\frac{1}{2}$) Buffalo	at	\$.
16	Ft. in. G. I. Pipe at	at	\$.
	Nipples	in. at	\$.
	Bushings	to in. at	\$.
	Red'g Coup	to in. at	\$.
	Inc'g Coup	to in. at	\$.
	Union	in. at	\$.
	Meter	in. at	\$.
	Cu. Yds. Br. Stone at		\$.
	Cu. Yds. Sand at		\$.
	Bags Cement at		\$.
	Paving Brick { Mack Red Asphalt } at		\$.
3	Hrs. Foreman at		\$.
14	Hrs. Common Labor at		\$.
	Hrs. Mason at		\$.
	Hrs. at		\$.
	Hrs. at		\$.
2	Builders Use of Water		\$.
		at	\$.
		at	\$.
		at	\$.
Total			\$ 16.49

Labor and Material Report June 10 1925

$3\frac{1}{4}$ " tap at 12 Madison at



6" Main Elev. of Main at tap 4.5

Gate at ● Gate at ●

● Curb Box

check for Copper