


Labor and Materials

Copper	} Connection.	3/4"	.....	\$. 96.
Lead				
Curb	} Cock Valve P.S.&V.	3/4 in	.....	\$. 1.33
Service Box				
Old returned	} Short 3 1/2 x 4 1/2 Long 4 1/2 x 6 1/2 Buff. or Railway		.....	\$. 1.35
2 1/2 Ft. 3/4 in.				
	} Copper Galv. Iron Cast Iron	} Pipe at 15	.....	\$. 3.60
Nipples				
Bushings	..... to .....	in. at .....	.....	.....
Red'g Inc'g	} Couplings..... to .....	in. at .....	.....	.....
Union.....				
Meter.....	in. at .....	.....	.....	.....
Lbs. Br. Stone	at .....	.....	.....	.....
Lbs. Sand	at .....	.....	.....	.....
Bags Cement	at .....	.....	.....	.....
Paving Brick	} Mack Red Asphalt	} at .....	.....	.....
Lead Joints				
Leadite Joints	at .....	.....	.....	.....
2 Hrs. Foreman	at 6 1/2	.....	.....	\$. 1.25
4 Hrs. Chief Labor	at 6 1/2	.....	.....	\$. 2.50
10 Hrs. Common Labor	at 4 1/2	.....	.....	\$. 4.50
8 Hrs. Mason	at 50	.....	.....	\$. 4.00
Hrs. Masons Helper	at .....	.....	.....	.....
Hrs. Compressor	at .....	.....	.....	.....
Compensation Ins	.....	.....	.....	.....
Trucking	.....	.....	.....	.....
Builders Use of Water	Patch	.....	.....	.....
Total \$.				25.87

636 29  
 Labor and Material Report 3/24/36 1936  
 23 Madison St  
  
 6" Main  
 Elev of Main at tap 5'  
 Gate at ● Gate at ●  
 ● Curb Box  
 Old tap disconnected  
 [Signature]