

Labor and Materials

| | | | | |
|------|-----------------------|---------------------|---------|----|
| 1 | Copper Lead | Connection | 3/4" | \$ |
| 1 | Curb | Cock Valve | 3/4" in | \$ |
| Same | Service Box | T. S. & V. | | \$ |
| | Old returned | Short 3 1/2 x 4 1/2 | | \$ |
| | | Long 4 1/2 x 5 1/2 | | \$ |
| | | Buff. or Rdway | | \$ |
| 24 | 3/4 in. | Copper | Pipe at | \$ |
| | | Galv Iron | | \$ |
| | | Cast Iron | | \$ |
| | Nipples | in. at | | \$ |
| | Bushings | to in. at | | \$ |
| | Red'g Inc'g | Conplings to in. at | | \$ |
| | Union | in. at | | \$ |
| | Meter | in. at | | \$ |
| | Lead Joints | at | | \$ |
| | Leadite Joints | at | | \$ |
| | Hrs. Foreman | at | | \$ |
| | Hrs. Chauffeur | at | | \$ |
| | Hrs. Tapper | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Labor | at | | \$ |
| | Hrs. Compressor | at | | \$ |
| | Compensation Ins. | | | \$ |
| | Trucking | | | \$ |
| | Builders Use of Water | | | \$ |
| | Tap by Gifford & Co | | | \$ |
| | 7-19-56 | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |
| | | | | \$ |

St. **12V**
 Pt. **8**
 Ave. No. **8**

Melrose
 Name of Owner
Leo E. Vaissiere

Labor and Mat'l. Report **July 19 1956**



6" Main
 Elev. of Main at tap **5'**
 Gate at ● Gate at ●

● Curb Box