

LABOR AND MATERIALS

1 Copper } Connection 1 1/2" \$
 Lead }
 1 Curb } Cock } 2 in. \$
 } Valve }
 } T. S. & V. }
 1 Service box { Short 3 1/2 x 4 1/2 }
 Old returned { Long 4 1/2 x 5 1/2 } small \$
 } Buff or Rdway }
 9 Ft. 2 in. { Copper } Pipe at \$
 } G. I. }
 } C. I. }
 1 Nipples 2 in. at Brass Elbow, \$
 Bushings to in. at \$
 1 Red'g } Coupl'gs 2" 177ale Adapter \$
 Inc'g } to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man-1 at \$
 Hrs. Water Maint. Man-2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor¹ at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 Tap by Kelly & Co. \$
 10-2-163. \$
 O'head \$
 \$

St. Maple
 PL
 Ave. No. 100

Name of Owner
First Baptist Church

Labor and Mat'l. Report Oct. 2 1963

6" Main Elev. of Main at tap 5 1/2

Gate at • Gate at •

TAX ID # 303.17-9-9

• Curb Box

LSM-5C-3-10-61