

### Labor and Materials

Copper } Connection.....	\$
Lead } .....	\$
Curb { Cock } .....	\$
{ Valve } .....	\$
{ T. S. & V. } .....	\$
Service Box { Short 3½ x 4½ } .....	\$
Old returned { Long 4½ x 5½ } .....	\$
{ Buff. or Rdway } .....	\$
Ft. .... in. { Copper } Pipe at.....	\$
{ Galv. Iron } .....	\$
{ Cast Iron } .....	\$
Nipples ..... in. at.....	\$
Bushings ..... to..... in. at.....	\$
Red'g } Couplings..... to..... in. at.....	\$
Inc'g } .....	\$
Union ..... in. at.....	\$
Meter ..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick { Mack } at.....	\$
{ Red } .....	\$
{ Asphalt } .....	\$
Lead Joints at.....	\$
Leadite Joints at.....	\$
Hrs. Foreman at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
Hrs. Compressor at.....	\$
Compensation Ins.....	\$
Trucking .....	\$
Builders' Use of Water.....	\$
Total \$.....	\$

Labor and Material Report

July 19 1926

no 117 maple st

vacant lot

can't find

● Curb Box

Main

Elev. of  
Main at tap

Gate at ●

● Gate at

● Curb Box