

Labor and Materials

1. Lead Connection	\$
..... Curb Cock	\$
..... Service Box { Short 3 1/2 x 4 1/2 Old returned { Long 4 1/2 x 5 1/2 Buffalo	\$
21. Ft. 1" in. G. I. Pipe at	\$
..... Nipples..... in. at	\$
..... Bushings to..... in. at	\$
..... Red'g Coup..... to..... in. at	\$
..... Inc'g Coup..... to..... in. at	\$
..... Union..... in. at	\$
..... Meter..... in. at	\$
..... Cu. Yds. Br. Stone at	\$
..... Cu. Yds. Sand at	\$
..... Bags Cement at	\$
..... Paving Brick { Mack Red Asphalt } at	\$
2. Hrs. Foreman at	\$
8. Hrs. Common Labor at	\$
2. Hrs. Mason at <i>Parrot</i>	\$
2. Hrs. <i>factory</i>	at \$
..... Hrs.	at \$
<i>for</i> Builders' Use of Water	\$
..... at	\$
<i>Truck l.o.d.</i>	at \$
..... at	\$
<i>Pavement</i>	at \$
..... at	\$
Total	\$ 28.57

Labor and Material Report *May 22* 19 *28*

3/4" tap at 137 Nipple at (old)



6" Main Elev. of Main at tap. *5' 11"*

Gate at ● ● Gate at
TAX ID # 303.17-18-9



