

## LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$	\$ 1.35
1 Lead } Connection $\frac{3}{4}$	\$ 1.80
1 Curb } Cock Valve	\$ 1.80
1 F.S. & V. } $\frac{3}{4}$ in.	
1 Service Box } Short $3\frac{1}{2} \times 4\frac{1}{2}$	\$ 4.32
Old returned } Long $4\frac{1}{2} \times 5\frac{1}{2}$	
} Buff or Rdway	
24 Ft. $\frac{3}{4}$ in. } Copper Pipe at $\frac{1}{8}$	\$ 4.32
} Galv Iron	
} Cast Iron	
Nipples .. in. at ..	\$ ..
Bushings .. to .. in. at ..	\$ ..
Red'g } Couplings .. to .. in. at ..	\$ ..
Inc'g ..	
Union .. in. at ..	\$ ..
Meter .. in. at ..	\$ ..
2 Lead Joints at <i>Lead to Man</i>	\$ 30
Leadite Joints at <i>com.</i>	\$ ..
Hrs. Foreman at ..	\$ 1.30.14
2 Hrs. Chauffeur at <i>6.8.14</i>	\$ 7.56.13
11 Hrs. Tapper at <i>7</i>	\$ 6.60.15
11 Hrs. Labor at <i>60</i>	\$ ..
Hrs. Labor at ..	\$ 88
1 Hrs. Compressor at <i>8.7.14</i>	\$ 46
Compensation Ins. ..	\$ 1.00
Trucking ..	\$ 11.70
Builders Use of Water ..	\$ ..
<i>Tap by Messer</i>	\$ ..
2 Holes $5 \times 3$ Each	\$ ..
<i>Tap on Cherry St</i>	\$ 39.17

St. Maple  
Pl. Maple  
Ave. No. 742

---

Name of Owner Fitzgerald

---

Labor and Mat'l. Report Aug 10 1913

Maple St

Cherry St

● Curb Box

---

4" Main Elev. of Main at tap. 6'

Gate at ● ● Gate at

TAX ID # 303.17-10-29

---

● Curb Box