

### Labor and Materials

Copper	Lead	Connection	\$	2.70				
Curb	Cock Valve	T. S. & V.	in.	\$	2.39			
						Service Box	Short 3 1/2 x 4 1/2	\$
Old returned	Long 4 1/2 x 5 1/2	Buff. or Rdway						
2 1/2 Ft.	in.	Copper Galv. Iron	Pipe at	\$	6.48			
Nipples	in.	at	\$					
Bushings	to	in.	at	\$				
Red'g Inc'g	Couplings	to	in.	at	\$			
Union	in.	at	\$					
Meter	in.	at	\$					
Lbs. Br. Stone	at	\$						
Lbs. Sand	at	\$						
Bags Cement	at	\$						
Paving Brick	Mack Red Asphalt	at	\$					
					Lead Joints	at	\$	
					Leadite Joints	at	\$	
5 Hrs.	Foreman	at	\$	3.13				
1 Hrs.	Common Labor	Tappet @ 50	\$	.50				
15 Hrs.	Common Labor	at	\$	6.75				
Hrs.	Mason	at	\$					
Hrs.	Mason's Helper	at	\$					
1 Hrs.	Compressor	at	\$	1.50				
Compensation	Ins		\$	.32				
Trucking			\$	1.-				
Builders' Use of Water	Patel		\$	25.-				
Total \$				51.22				

30-191

Labor and Material Report

19

1485 Maple Street



Main

Elev of Main at tap

Gate at

29' to main

Gate at

Curb Box

old tap disconnected

TAX ID # 303.17-18-6