

LABOR AND MATERIALS

1 Copper Lead	Connection	3/4	\$	2.80
1 Curb	Clock Valve T.S. & V.	3/4 in.	\$	3.60
1 Service box Old returned	Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway		\$	5.80
6 Ft.	3/4 in. Copper Galv. Iron Cast Iron	Pipe at	35	\$ 2.10
Nipples	in. at		\$	
Bushings	to in. at		\$	
Red'g Inc'g	Couplings	to in. at	\$	
Union	in. at		\$	
Meter	in. at		\$	
Lead Joints	at		\$	
Compound Joints	at		\$	
Hrs. Foreman	at		\$	
Hrs. Chauffeur	at		\$	
Hrs. Tapper	at		\$	
Hrs. Labor	at		\$	
Hrs. Labor	at		\$	
Hrs. Compressor	at		\$	
Compensation Ins.			\$	
Trucking			\$	1-
Builders Use of Water			\$	
			\$	
			\$	
			\$	
			\$	
			\$	

11/11

St. Maple
Pl. Maple
Ave. No. 146

Name of Owner Del Signore

Labor and Mat'l. Report Aug 16 19 47

14'9" 38'9" 14'9" ST

Cherry ST.

4 Main Elev. of Main at tap 6

Gate at ● Gate at ●

● Curb Box

LSM-5C-6-1-45 Tap on Cherry St