

### LABOR AND MATERIALS

Copper } Connection.....	\$.....
Lead } .....	\$.....
Curb } Cock Valve } .....	in. .... \$.....
} T. S. & V. } .....	} .....
Service Box } Short 3½x4½ } .....	\$.....
Old returned } Long 4½x5½ } .....	} .....
} Buff or Rdway } .....	} .....
Ft. .... in. } Copper } Pipe at.....	\$.....
} Galv Iron } .....	} .....
} Cast Iron } .....	} .....
Nipples ..... in. at .....	\$.....
Bushings ..... to ..... in. at .....	\$.....
Red'g } Couplings ..... to ..... in. at .....	\$.....
Inc'g } .....	} .....
Union ..... in. at .....	\$.....
Meter ..... in. at .....	\$.....
Lead Joints at .....	\$.....
Leadite Joints at .....	\$.....
Hrs. Foreman at .....	\$.....
Hrs. Chauffeur at .....	\$.....
Hrs. Tapper at .....	\$.....
Hrs. Labor at .....	\$.....
Hrs. Labor at .....	\$.....
Hrs. Compressor at .....	\$.....
Compensation Ins. ....	\$.....
Trucking .....	\$.....
Builders Use of Water .....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....
.....	\$.....

St.  
Pt.  
Ave. No. 151

Maple

Name of Owner  
T.J. Kennedy

Labor and Mat'l. Report FEB 5 - 1941 19



..... Main Elev. of  
Main at tap.....

Gate at ● ● Gate at

● Curb Box

2" Line