

Labor and Materials

Copper } Connection.....	3	\$ 2.70
Lead }		
Curb } Cock Valve }	2	\$ 2.39
} T-S & V. }		
Service Box } Short 3/4x1 1/4 }		\$ 1.45
Old returned } Long 1 1/2x5/8 }		
} Buff. or Rdway }		
2 1/2 Ft. in. } Copper } Pipe at.....	3	\$ 6.48
} Galv. Iron }		
} Cast Iron }		
Nipples..... in. at.....		\$
Bushings..... to..... in. at.....		\$
Red'g } Couplings..... to..... in. at.....		\$
Inc'g }		
Union..... in. at.....		\$
Meter..... in. at.....		\$
Lbs. Br. Stone at.....		\$
Lbs. Sand at.....		\$
Bags Cement 'at.....		\$
Paving Brick } Mack } at.....		\$
} Red }		
} Asphalt }		
Lead Joints at.....		\$
Leadite Joints at.....		\$
2 Hrs. Foreman at.....		\$ 1.87
1 Hrs. Common Labor at.....	Tapper	\$ 50
1.9 Hrs. Common Labor at.....		\$ 8.55
Hrs. Mason at.....		\$
Hrs. Mason's Helper at.....		\$
3 Hrs. Compressor at.....		\$ 4.50
Compensation Ins.....		\$ 34
Trucking.....		\$ 1.-
Builders' Use of Water.....		25.-
Total \$		54.99

Labor and Material Report

Aug 2, 19

151-153 South Street



Main Elev of Main at tap

Gate at ● ● Gate at

● Curb Box

old tap disconnected
Morris Factory