

Labor and Materials

| | | |
|--|---|----------|
| Copper } Connection..... | 3 | \$ 2.70 |
| Lead } | | |
| Curb } Cock Valve } | 3 | \$ 2.39 |
| } T. S. & V. } | | |
| Service Box } Short 3 1/2 x 4 1/2 } | 1 | \$ 1.45 |
| Old returned } Long 4 1/2 x 5 1/2 } | | |
| } Buff. or Rdway } | | |
| Ft. in. } Copper } Pipe at..... | 3 | \$ 1.89 |
| } Galv. Iron } | | |
| } Cast Iron } | | |
| Nipples..... in. at..... | | \$ |
| Bushings..... to..... in. at..... | 3 | \$ 1.10 |
| Red'g } Couplings..... to..... in. at..... | | \$ |
| Inc'g } | | |
| Union..... in. at..... | | \$ |
| Meter..... in. at..... | | \$ |
| Lbs. Br. Stone at..... | | \$ |
| Lbs. Sand at..... | | \$ |
| Bags Cement at..... | | \$ |
| Paving Brick } Mack } at..... | | \$ |
| } Red } | | |
| } Asphalt } | | |
| Lead Joints at..... | | \$ |
| Leadite Joints at..... | | \$ |
| 4 1/2 Hrs. Foreman at..... | | \$ 2.82 |
| 1 Hrs. Common Labor at. Tapper | | \$.50 |
| 1.2 Hrs. Common Labor at..... | | \$ 5.85 |
| Hrs Mason at..... | | \$ |
| Hrs Mason's Helper at..... | | \$ |
| 2 Hrs. Compressor at..... | | \$ 3.00 |
| Compensation Ins..... | | \$ 2.88 |
| Trucking..... | | \$ 1.00 |
| Builders' Use of Water..... | | \$ 25.00 |
| Total \$. | | 46.98 |

30-187

Labor and Material Report Aug 2 1930

15th Ward



Curb Box

Main

Elev of Main at tap 53

Gate at ●

● Gate at

● Curb Box

Old tap disconnected