

LABOR AND MATERIALS

1	Copper Lead	Connection	$\frac{3}{4}$	\$	1.59
1	Curb	Cock Valve T.S. & V.	$\frac{3}{4}$ in.	\$	2.74
1	Service Box Old returned	Short $3\frac{1}{2} \times 4\frac{1}{2}$ Long $4\frac{1}{2} \times 5\frac{1}{2}$ Buff or Rdway		\$	1.82
26	Ft.	$\frac{3}{4}$ in.	Copper Galv Iron Cast Iron	Pipe at	19 \$ 4.94
	Nipples	in. at		\$	
	Bushings	to in. at		\$	
	Red'g Inc'g	Couplings to in. at		\$	
	Union	in. at		\$	
	Meter	in. at		\$	
	Lead Joints	at		\$	
	Leadite Joints	at		\$	
1	Hrs. Foreman	at W. W. M.	77	\$	5.39
2	Hrs. Chauffeur	at	62.75	\$	7.31
2	Hrs. Tapper	at		\$	4.81
2	Hrs. Labor	at	60	\$	1.20
	Hrs. Labor	at		\$	
2	Hrs. Compressor	at	97.12	\$	1.75
	Compensation Ins.			\$	39
	Trucking			\$	1
	Builders Use of Water			\$	9
	Tap by Miller			\$	
				\$	
				\$	
	1 Hole 6 X 3			\$	
				\$	
				\$	36.00

14 / 14

St. Maple

Pl.

Ave. No. 159-161

Name of Owner Fitzgerald

Labor and Mat'l. Report June 6 1940

159-161

Curb Box

6" Main

Elev. of Main at tap 5"

Gate at ●

● Gate at

● Curb Box

