

Labor and Materials

Copper } Connection.....	\$ 2.70
Lead }	\$ 2.39
Curb } Cock Valve }	\$ 1.55
} T. S. & V. }	\$ 7.56
Service Box } Short 3/4x4 1/2 }	\$
Old returned } Long 4 1/2x5 1/2 }	\$
} Butt or ledway }	\$
28 Ft. in. } Copper } Pipe at.....	\$
} Galv-Iron }	\$
} Cast-Iron }	\$
Nipples..... in. at.....	\$
Bushings..... to..... in. at.....	\$
Red'g } Couplings..... to..... in. at.....	\$
Inc'g }	\$
Union..... in. at.....	\$
Meter..... in. at.....	\$
Lbs. Br. Stone at.....	\$
Lbs. Sand at.....	\$
Bags Cement at.....	\$
Paving Brick } Mack } at.....	\$
} Red }	\$
} Asphalt }	\$
Lead Joints at.....	\$
Leadite Joints at.....	\$
4 1/2 Hrs. Foreman at.....	\$ 2.82
6 Hrs. Common Labor at.....	\$ 2.70
Hrs. Common Labor at.....	\$
Hrs. Mason at.....	\$
Hrs. Mason's Helper at.....	\$
2 1/2 Hrs. Compressor at.....	\$ 3.75
Compensation Ins.....	\$.17
Trucking.....	\$
Builders' Use of Water.....	\$
Total \$	49.14
	24.64

30-195

Labor and Material Report

19

173 Maple Street



6 Main

Eley of Main at tap 6

Gate at ●

● Gate at

TAX ID # 303.17-20-6

● Curb Box

New house