

### Labor and Materials

1	Copper	Connection	3/4"	\$
1	Lead			\$
1	Curb	Cock Valve	3/4" Oriseal	\$
1	same	T. S. & V.		\$
	Service Box	Short	3 1/2 x 4 1/2	\$
	Old returned	Long	4 1/2 x 5 1/2	
25	3/4"	Buff. or Rdway		\$
	Ft.	Copper	Pipe at	\$
		Galv Iron		\$
		Cast Iron		\$
	Nipples	in. at		\$
	Bushings	in. to in. at		\$
	Red'g	Conplings	to in. at	\$
	Inc'g			
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Chauffeur	at		\$
	Hrs. Tapper	at		\$
	Hrs. Labor	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
	Tap by Giggord & Co.			\$
	9-28-64			\$

Maple St. 189-191  
 Ave. No.

Name of Owner Helen L. Bromley  
 Occupant Adirondack Glass Co.

Labor and Mat'l. Report Sept. 28, 1964



6" Main Elev. of 5-6'  
 Main at tap

Gate at ● ● Gate at

● Curb Box