

LABOR AND MATERIALS

1 Copper } Connection $\frac{3}{4}$ " \$
 Bead }
 1 Curb } Cock } $\frac{3}{4}$ in. (MAYN) \$
 Valve } (OYISEAL)
 T.S. & V. }
 1 Service box { Short $3\frac{1}{2}$ x $4\frac{1}{2}$ } OYISEAL
 Old returned { Long $4\frac{1}{2}$ x $5\frac{1}{2}$ } \$4' x 5'
 Buff or Rdway }
 10 Ft. $\frac{3}{4}$ in. { Copper } Pipe at \$
 C.I. }
 C.I. }
 Nipples in. at \$
 Bushings to in. at \$
 Red'g }
 Inc'g } Coupl'gs to in. at \$
 Union in. at \$
 Meter in. at \$
 Lead Joints at \$
 Compound Joints at \$
 Maintenance Foreman \$
 Hrs. Water Maint. Man-1 at \$
 Hrs. Water Maint. Man-2 at \$
 Hrs. Garage Foreman at \$
 Hrs. Labor- at \$
 Hrs. Compressor at \$
 Compensation Ins. at \$ per C \$
 Trucking \$
 Pav't Patch \$
 Tap Made By GIFFORD \$
 O'head NOV-26-1973 \$
 \$

St. Pt. Ave. No. 196
 Maple
 Name of Owner
 Blanche Grube
 Labor and Mat'l. Report NOV 26 1973

26'-8" 34'-11"
 Curb Box
 6" Main Elev. of Main at tap 6'
 Gate at • Gate at
 • Curb Box

LSM-5C-6-1-67