

LABOR AND MATERIALS

1	Copper Lead	} Connection	3/4"	\$
1	Curb			
1	Service box Old returned	} { Short 3 1/2 x 4 1/2 Long 4 1/2 x 5 1/2 Buff or Rdway.	\$	
24	Ft. 3/4 in.			} { Copper Gal. Gal.
	Nipples	in. at	\$	
	Bushings	to in. at	\$	
	Red'g Inc'g	} Coupl'gs	to in. at	\$
	Union			
	Meter	in. at	\$	
	Lead Joints at	\$		
	Compound Joints at	\$		
	Maintenance Foreman	\$		
	Hrs. Water Maint. Man-1 at	\$		
	Hrs. Water Maint. Man-2 at	\$		
	Hrs. Garage Foreman at	\$		
	Hrs. Labor at	\$		
	Hrs. Compressor at	\$		
	Compensation Ins. at \$	per C	\$	
	Trucking	\$		
	Pav't Patch	\$		
	<i>Tap made by St. Johns Co</i>			
	<i>July 25-1973</i>			
	O'head	\$		
		\$		

St.
No. 203

Maple

Name of Owner
Dennis Hannan

Labor and Mat'l. Report July 25 1973

20'-2" 12'-6" ● Curb Box

6" Main Elev. of Main at tap 6'

Gate at ● ● Gate at

TAX ID # 303.17-22-3

● Curb Box

LSM-5C-6-1-67