

LABOR AND MATERIALS

1	Copper	Connection	3/4"	\$
1	Lead	Cock	3/4 in.	\$
1	Curb	Valve	3/4 in.	\$
		T.S. & V.		
1	Service box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
		Buff or Rdway		\$
8	3/4 in.	Copper	Pipe at	\$
		<del>C.I.</del>		
		<del>C.I.</del>		
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g	Coupl'gs to in. at		\$
	Inc'g			\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Compound Joints	at		\$
	Maintenance Foreman			\$
	Hrs. Water Maint. Man-1	at		\$
	Hrs. Water Maint. Man-2	at		\$
	Hrs. Garage Foreman	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins. at \$	per C		\$
	Trucking			\$
	Pav't Patch			\$
	Tap by J. J. Gordan & Poley			\$
	4-10-57			\$
	O'head			\$

St. Maple No. 204

Name of Owner A10175017

Labor and Mat'l. Report Apr. 10 1957

6" Main                      Elev. of Main at tap 6"

Gate at ●    ● Gate at

● Curb Box

TAX ID # 303.17-14-14

L. M-5C-2-1-54