

Labor and Materials

1	Copper Lead	Connection	3/4"	\$
1	Carb	Cock Valve T.S. & V.	3/4" oriseal	\$
1	Service Box	Short 3 1/2 x 4 1/2		\$
	Old returned	Long 4 1/2 x 5 1/2		\$
10	3/4" in.	Buff. or Rdway		\$
		Copper		\$
		Galv Iron		\$
		Cast Iron		\$
	Nipples	in. at		\$
	Bushings	to in. at		\$
	Red'g Inc'g	Conplings to in. at		\$
	Union	in. at		\$
	Meter	in. at		\$
	Lead Joints	at		\$
	Leadite Joints	at		\$
	Hrs. Foreman	at		\$
	Hrs. Chauffeur	at		\$
	Hrs. Tapper	at		\$
	Hrs. Labor	at		\$
	Hrs. Labor	at		\$
	Hrs. Compressor	at		\$
	Compensation Ins.			\$
	Trucking			\$
	Builders Use of Water			\$
	Tap by Giggard			\$
	Tap & Co.			\$
	6-1-63.			\$
				\$
				\$

St. Maple
 Pl. 210
 Ave. No. 210

Name of Owner Sheehan.

Labor and Mat'l. Report June 1 1963

House 27'4" House 30'6"

Curb Box

6 C.I. Main Elev. of Main at tap 6'

Gate at ● ● Gate at

TAX ID # 303.17-14-18

● Curb Box