

LABOR AND MATERIALS

| | | | | |
|-------------------------------|--|-------------------------------|-----------------|----|
| Copper | } Connection | | \$ | |
| Lead | | | | |
| Curb | } Clock Valve T. S. & V. | in. | \$ | |
| Service box | | | | |
| Old returned | } Short 3 1/2 X 4 1/2 Long 4 1/2 X 5 1/2 Buff or Rdway | | \$ | |
| Ft. in. | | } Copper Galv. Iron Cast Iron | } Pipe at | \$ |
| Nipples | | | | |
| Bushings | to | in. at | \$ | |
| Red'g Inc'g | } Couplings | to | in. at | \$ |
| Union | | in. at | \$ | |
| Meter | in. at | \$ | | |
| Lead Joints at | | \$ | | |
| Compound Joints at | | \$ | | |
| Hrs. Foreman at | | \$ | | |
| Hrs. Chauffeur at | | \$ | | |
| Hrs. Tapper at | | \$ | | |
| Hrs. Labor at | | \$ | | |
| Hrs. Labor at | | \$ | | |
| Hrs. Compressor at | | \$ | | |
| Compensation Ins. | | \$ | | |
| Trucking | | \$ | | |
| Builders Use of Water | | \$ | | |
| <i>Measured by Wanshok by</i> | | | | |
| <i>G.D.S.</i> | | | | |
| | | | \$ | |
| | | | \$ | |
| | | | \$ | |

St. Maple
 Pl. _____
 Ave. No. 222

Name of Owner _____

Labor and Mat'l. Report June 1945

222

80" 66"

● Curb Box

| | |
|-----------|----------------------|
| Main | Elev. of Main at tap |
| Gate at ● | ● Gate at |

● Curb Box

TX ID # 303.17-15-15

LSM-5C-6-1-45