

Labor and Materials		
1	Copper } Connection. $\frac{3}{4}$ "	\$ 32.0
	Lead	
1	Curb } Cock } $\frac{3}{4}$ " in.	\$ 1.00
	} Valve	
	} T.S. & V.	
1	Service Box } Short 31 x 41	\$ 1.40
	Old returned } Long 41 x 51	
		Buff. or Rdway
11	Ft. $\frac{3}{4}$ " in. } Copper } Pipe at.	\$ 2.42
		Galv. Iron
		Cast Iron
	Nipples..... in. at.	\$
	Bushings..... to..... in. at.	\$
	Red'g } Couplings..... to..... in. at.	\$
	Inc'g }	
	Union..... in. at.	\$
	Meter..... in. at.	\$
	Lbs. Br. Stone at.	\$
	Lbs. Sand at.	\$
	Bags Cement at.	\$
	Paving Brick } Mack } at.	\$
		Red
		Asphalt
	Lead Joints at.	\$
	Leadite Joints at.	\$
9	Hrs. Foreman at. 62.5	\$ 563
	Hrs. Common Labor at.	\$
6	Hrs. Common Labor at. 40.8	\$ 244
	Hrs. Mason at.	\$
	Hrs. Mason's Helper at.	\$
1	Hrs. Compressor at.	\$ 2.80
	Compensation Ins.	\$ 26
	Trucking	\$ 1.00
	Builders' Use of Water.	\$
Total \$		1935

27-99

Labor and Material Report 17 1927

3/4 tap at 14" curb east

Miller and Maple st

Catch Basin

Main

Elev. of Main at tap 111

Gate at

Gate at

Curb Box

This Place
MOVED

SHUT OFF AT
CURB,

First Nat. Bank
DRIVEN IN